


Packing List

- RBA-700 Industrial Controller
- Quick Installation Guide

Mechanical



Power In: DC +12V

	PIN NO.	1	2
	1	VIN	GND


PIN ASSIGNMENT—RS-485

	PIN NO.	COM3、COM4 RS-485
	1	ISO_GND
	2	D-
	3	D+

PIN ASSIGNMENT—RS232 FULL

PIN Number	COM1、COM2
	RS232 FULL
1	DCD
2	RX
3	TX
4	DTR
5	GND
6	DSR
7	RTS
8	CTS
9	RI

Parallel Port



Net Name	PIN Number		Net Name
STBn	1	14	AFDn
PD0	2	15	ERRn
PD1	3	16	INITn
PD2	4	17	SLINn
PD3	5	18	GND
PD4	6	19	GND
PD5	7	20	GND
PD6	8	21	GND
PD7	9	22	GND
ACKn	10	23	GND
Busy	11	24	GND
PE	12	25	GND
SLCT	13		

General Information

Dimension: 188(W)x145(H)x55(mm)


Net weight: 1.3kg

Operating temperature: 0°C ~ 40°C, 5 to 85% RH

Power supply: +12V DC


Warning: Improper power input might damage the device

LAN



PIN Number	LAN
1	TX+
2	TX-
3	RX+
4	NC1
5	NC1
6	RX-
7	NC2
8	NC2

USB HOST



PIN Number	USB HOST
1	USB VCC
2	USB D-
3	USB D+
4	USB GND