





























<p>A1</p>  <p>X1</p>	<p>A2</p>  <p>X2</p>	<p>A3</p>  <p>X4</p>	<p>A4</p>  <p>X2</p>	<p>A5</p>  <p>X2</p>
<p>A6</p>  <p>X1</p>	<p>A7</p>  <p>X4</p>	<p>A8</p>  <p>X2</p>	<p>A9</p>  <p>X1</p>	<p>A10</p>  <p>X1</p>
<p>A11</p>  <p>X2</p>	<p>A12</p>  <p>X1</p>	<p>A13</p>  <p>X3</p>	<p>A14</p>  <p>ST4X14=9</p>	<p>A15</p>  <p>X8</p>
<p>A16</p>  <p>X1</p>	<p>A17</p>  <p>L=1.5M X1</p>	<p>A18</p>  <p>X8</p>	<p>A19</p>  <p>ST4X12=4</p>	<p>A20</p>  <p>ST4X40=8</p>
<p>A21</p>  <p>ST4X10=27</p>	<p>A22</p>  <p>X1</p>	<p>A23</p>  <p>X2</p>	<p>A24</p>  <p>X1</p>	<p>A25</p>  <p>X2</p>
<p>A26</p>  <p>X1</p>	<p>A27</p>  <p>X1</p>	<p>A28</p>  <p>X1</p>	<p>Ø2.8</p> 