

Table of Contents

- 1. Vediamo - Basic knowledge - Part ONE
 - 1.0 Getting started
 - 1.1 Preparation of CBFs for Carlines
 - 1.1.1 How to find the CBF and SMR-D Folder
 - 1.1.2 Explanations of ECUs and CBF names
 - 1.1.3 Explanations for SMR-D Files
 - 1.2 SDconnect C4 usage
 - 1.2.1 Choosing Modul for vediamo usage (SMR-D & CBF)
 - 1.3 Open/load ECU (using prepared CBFs)
 - 1.3.1 Turning off CBF consistency check
 - 1.4 Certain important procedures
 - 1.4.1 Hard Reset should be done after the variant coding
 - 1.4.2 Eeprom write
 - 1.4.3 ECU secure access for coding
 - 1.4.4 Variant Coding
 - 1.5 Backup ECU Data
 - 1.5.1 Backup ECU ID Info
 - 1.5.2 Backup variant coding
 - 1.5.3 Backup Measurement and calibration data
 - 1.6 Restoring ECU Data
 - 1.6.1 Restore variant codings by copy & paste
 - 1.6.2 Restore measurement/calibration data from former ECU
 - 1.7 Seed key explanation
 - 1.7.1 ECUs with seed key
 - 1.7.2 UDS/Manual Method - Seed key insertion (fast method)
 - 1.7.3 Function search for Seed Key insertion (long method)
- 2. Vediamo - Variant Coding - Part TWO
 - 2.0 Possible codings and changes in certain carlines
 - 2.0.1 R171
 - 2.0.2 R230
 - 2.0.3 R172 R231
 - 2.0.4 W203 S203 W463
 - 2.0.5 W204 S204 X204
 - 2.0.6 w205 s205 x253
 - 2.0.7 W211 S211 W219 W209
 - 2.0.8 W218 X218
 - 2.0.9 W212 S212 A207 C207
 - 2.0.10 W213
 - 2.0.11 W176 W246 W117 C117 X117 X156
 - 2.0.12 W251 W164 X164
 - 2.0.13 W166 X166 W292
 - 2.0.14 W221 W216
 - 2.0.15 W222 W217
 - 2.0.16 W447
 - 2.0.17 639
 - 2.0.18 W169 W245
 - 2.1 Turn signal flasher changed from 3x to 5x
 - 2.1.1 Carlines: 117 156 166 W176 W246 C292 463
 - 2.1.2 Carlines: 172 190 197 197_ECELL 204 207 212 218 231
 - 2.1.3 Carlines: w213
 - 2.1.4 Carlines: w205 217 222 w253
 - 2.2 Comand NTG 4 - CD ripping mode
 - 2.2.1 CD ripping mode
 - 2.2.2 Show speed limit signs (map data)
 - 2.2.3 Comand Language change
 - 2.2.4 DVD-Region change
 - 2.2.5 Show speed limit signs (mpc/Camera data)
 - 2.2.6 PIN code insertion
 - 2.3 Instrument cluster
 - 2.3.1 Turn on the remaining fuel liters
 - 2.3.2 Daylight menu activation
 - 2.3.3 ESP off menu activation
 - 2.3.4 Deactivate Seat belt warning
 - 2.3.5 MPC End of speedlimit show
 - 2.3.6 Changing tire pressure unit - Psi to bar - just mentioning no screenshots
 - 2.3.7 Changing temperature unit - just mentioning - no screenshots
 - 2.3.8 W212 - Activate language menu in cluster - just text
 - 2.5 Door closing, opening sound and volume change
 - 2.6 Start/Stop function remember last choice ? keeps turned off
 - 2.7 Speed limit assistant (GLA) activate all countrys
 - 2.8 Deactivate tire pressure control system
 - 2.9 Vmax change
 - 2.9.1 Possible velocities due to engine and carline - (1Car till now)
 - 2.10 Pedal characteristic curve Faster engine response
 - 2.11 PTC acoustic signal at first led
 - 2.12 Hold function after pushing brake once totally and second time then brake will be hold
 - 2.13 Hill start function keeps the brake at a hill in braking position
 - 2.14 Sidemarker
 - 2.14.1 Turn on sidemarker when turn signal
 - 2.14.2 Sidemarker activation even if USA coding is missing
 - 2.14.3 W205 - Disable sidemarker - US to ECE conversion - just text
 - 2.15 Air condition
 - 2.15.1 Temperature offset to set the air condition colder
 - 2.15.2 Ventilation bars in display turned on in auto modus
 - 2.15.3 Temperature change shown in Comand display
 - 2.15.4 Change Country coding
 - 2.16 Comand NGT 4.5 layout template to papyrus or silver
 - 2.17 Change of chassis height and damping to AMG
 - 2.18 Deactivation of airmatic due to hardware change of chassis (airmatic removed)
 - 2.19 Turn on LED bow with daylight - not tested - 204 / X204
 - 2.20 Retrofit Option - Adaptive Highbeam Assist - Code 608
 - 2.21 HUS possibilities - not tested
 - 2.21.1 AMG starting pic
 - 2.21.2 Speedlimit assistant in comand
 - 2.21.3 Video in motion (VIM) enable - not tested
 - 2.21.4 Comand Language change
 - 2.21.5 Turning on of ripping feature for cds
 - 2.21.6 Turning on AMG design variant
 - 2.21.7 AMG Sport option - needs to be tried out
 - 2.21.8 Video in Motion - VIM - not tested yet
 - 2.21.9 Video in Motion - VIM - not tested yet
 - 2.21.2 Turn on engineering mode
 - 2.22 Comand NTG 5.5
 - 2.22.1 Mirrorlink activation
 - 2.23 Exhaust sounddesign by engine ECU
 - 2.24 Fahrdynamik/Drive dynamic function by engine ECU
 - 2.25 Turning off car level sensors - just forum info
 - 2.26 Retrofit AMG parameters to NTG 5.x
 - 2.27 MP4 Trucks - vmax change - seed key needed
 - 2.28 Retrofit MPC Camera - just ecu mention
 - 2.29 Turning on curvematic - just mentioning ECUs - W211
 - 2.30 Retrofit/deactivate Blind Spot - just mentioning
 - 2.31 Deactivate or activate folding mirrors
 - 2.32 W212 or other - Taillights US to ECE - blinker coding - just text
 - 2.33 W212 - Static LED to Dynamic LED - just text
 - 2.34 Polish language or other in HUS_ENTRY - just text
 - 2.35 W205 Halogen to static LED - just text
 - 2.36 W205 - Taillight blinker US to ECE - just text
- 2.38 Trunk lid key closing
 - 2.38.1 W212 and others
 - 2.38.2 W221
 - 2.38.3 Normalization of trunk lid
- 2.39 W221 - possibilities
 - 2.39.1 KI221 - AMG & BRABUS Dumps - MHHAUTO URL links
 - 2.39.2 Key warning if leaving car
 - 2.39.3 Turning on pressure control
 - 2.39.4 KI221 Menuactivations
 - 2.39.5 Turning off seatbelt warning
- 2.40 DLR - Change daylight color into blue
- 2.41 Activate EDW - Alarm system (software) - Basic by horn
 - 2.41.1 W204 ands W212
 - 2.41.3 W176 and W246
- 2.42 IC scale at day bright - w212 Facelift
- 2.43 W205 Ambientlight (3colors)
- 2.44 Deactivation of valve exhaust systems (always open) R172 SLK 55AMG MY2014
- 2.45 Seat heating higher - 204, 207, 212, 218 (just ecu)
- 2.46 Deactivation of brake wear warning - W222, W217, W213, X253, W205

- 3. Millage check - which ECUs & Keys are involved
- 3.1 Millage ECUs
- 3.2 Millage in Keys
- 4. Flashing a ECU
- 4.1 Preparations before flashing
 - 4.1.1 How to find the correct CFF
 - 4.1.2 How to find the correct Telematic disks
- 4.2 Flashing a ECU with one CFF (which CFF and how)
- 4.3 Flashing a ECU with more than one CFF (not implemented yet)
- 5. Procedures
- 5.1 Sync IC to EZS (204) - not tested
- 5.2 SBC renew/reset by DAS - not tested
- 5.3 Entering Engineering Menu NTG 4.5 / 4.7
- 5.4 NTG 4.5 DVD video not activated after flash due to flash Japanese to ECE
- 5.5 7G Transmission - KÜB lock up
 - 5.5.1 DAS - with adaption
 - 5.5.2 vediamo - just lock up
- 5.6 NTG 2.5 - working at the bench without car
- 5.7 Switch KI/IC to AMG (204, 212, 216, 221) with FVDI
 - 5.7.1 Eeprom links (204, 221, 216)
 - 5.7.2 FVDI
 - 5.7.3 DASH/KI/IC adaption to car
- 5.9 IC204 Update from MY2012 to MY2014
- 5.10 Delete crashevents
- 5.11 Keyless go IC says Key battery empty
- 6. RETROFITs
- 6.1 Retrofit 204 rear led lights w DAS
- 6.2 W211 Retrofit Antitheft option - EDW - DAS
- 6.3 W169 / W 245 Speedlimiter
- 6.4 W205 - Retrofit full led taillights - just text
- 6.5 W176 folding mirrors
- 6.6. 205 Keyless Go entry
- 6.7 Speedlimit assist for certain carlines - what is needed
 - 6.7.1 Coding - just mentioning ECUs
- 6.8 Activation of drive dynamic seats R231, W212
- 6.9 Rear facelift lights - A207, C207, W212, S212 - without coding - PINS
- 6.10 Rear Camera - W205, S205, W222, W447 and X253
- 7. Services done by Users for Users (mhhauto)
- 7.1 Activation of AMG menu - IC204 and IC172 - who is performing this (person) - short how to but no seed key explanations
- 7.2 Regular coding services performed through TEAMVIEWER by user kmodel99
- 7.3 Telematik disks
- 7.4 original ECOM